

Diagnostics and analysis in MDPCT1

MDP Meeting March 1, 2021

Storan Stoyney for the FNAL/LBNL team US Magnet Development Program

Fermi National Accelerator Laboratory

3/1/2021

MDPCT1 tests

□ The magnet was first tested in Summer 2019 – TC1

- ✓ The training was stopped after we crossed a pre-defined quench current limit
- □ After some modifications related to end-support (discussed elsewhere) it was retested in Summer 2020
- MDPCT1 went through two more thermal cycles (TC2 and TC3)
 - \checkmark In TC2 the magnet retrained

3/1/2021

Office of

Science

 ✓ In TC3 the magnet showed very limited performance



MDPCT1 instrumentation

Voltage taps

- Strain gauges on coils, poles, bullets/rods and shell strain monitoring during cool down, warm up and quenches to build the full stress picture vs conditions
- Protection heaters for quench protection of the superconducting magnet
 ✓ In addition to heaters the magnet is protected by an energy extraction system
- **Quench** antenna for independent quench characterization

- Acoustic sensors for independent quench characterization
- **Temperature sensors** outside magnet or bore temperature



"Non-standard" instrumentation and diagnostics

U We deployed two types of **quench antenna** sensitive to the innermost layer transients

- ✓ There were only two quenches there, both in TC1
- ✓ Very good data but not much use for the overall quench analysis

Acoustic sensors

- ✓ Attempted new ("better") types in MDPCT1, failed to extract good data
- ✓ Reverted to "old" style in TC2/TC3, most ramps; **very good data**, useful for performance analysis

Temperature sensors in the bore

✓ Interesting data but also not much relevant for quenches in outer layers

Multi-channel nano-voltmeter

✓ Much upgraded version of our single channel splice measurement system (different electronics)

I will concentrate on the performance of non-standard (not universal at FNAL) techniques and/or ones crucial for analysis.

We did not have resources to analyze "spike data" yet though we took data in many ramps.

MDPCT1 voltage taps



Voltage tap data

- TC1 virtually all of layer 3 and 4 VTs lost due to cuts in layer 4 traces
 - ✓ Also lost all strain gauges there
 - Recovered all but one VT for TC2 and TC3 tests
- □ Other VTs were continuously fine
- We managed to identify well all quenches in TC2/TC3 tests



3/1/2021

U.S. DEPARTMENT OF

Office of

Science



TC2 data (segments with voltage rise,

Multi-channel nano-voltmeter ("MUX")

- **Temporarily in our hands**
 - ✓ Not perfectly fitted for our needs
 - ✓ Few channels we couldn't measure
 - ✓ Some had large noise (long segments)
 - ✓ Partially a "black box"

Office of

3/1/2021

We are developing a dedicated "MUX"

[V]	Ch1 (5c6_c7)										
-0.00015											
-0.000151	0 5 10 15 20 25 30 35 40 Some bias in first										
-0.000152	measurements Fach measurement										
-0.000153	observed is ~ 1 s long										
-0.000154											
-0.000155											
-0.000156											
-0.000157											
-0.000158											
-0.000159											
-0.00016											

FVAL 20-Channel Multiplexor



Front and back panels (20 channels)

	🔛 NV_Meter_Scan.vi	-	o x		
	File Edit View Project Operate Tools Window Help				
	🖷 🐼 🥥 💵		? 2		
	Folder	File Name			
	C:\Splice_Test_Data\MDPCT1b\NV_MUX\cvts9_16	5kA_Test			
Configuration panel	Samples/CH 10 Log? Connect Start Scan	BUSY Meter CRIO	CH SEL		
	Buffer Samples 12 Single Scan Disconnect Stop Scan	•••	CH2 CH3 CH4		
		Measurement CH	CH5 CH6		
	Enable Ratio Integration Units Integration Rate	0.00016736 10	CH7		
	Line Sync 🔽 🖞 Line Cycles 🖞 5		СН9		
	Autorange Range Value Sample Count Resolution	Period (ms) Sample	✓ CH10 ✓ CH11		
	Enable Delta	1043 -11	CH12		
	Analog Filter V Filter Window % Filter Count Filter Type		CH14		
	10 Moving	Status Temp	CH16		
	Update	Ready 29.18	CH17		
	COM Port & COM5 Reset ACAL		CH19 CH20		
	Mux Scan Ivproi/My Computer		2		
	Find Drivers and	Add-ons 👘 🍛 Comr	nunity and Suppo		

All measurements are sequential (no parallel read out)

Averages with limits (w w/o bias)

primarily Tom Cummings (engineer)



Splice resistance measurements with MUX



U.S. DEPARTMENT OF

ENERGY Science

Office of

3/1/2021

Old DAQ

TC1

Coil	Splice	R (nOhm)
2	A1-A2	0.61
2	B1-B2	0.39
3	A1-A2	0.35
3	B1-B2	0.44
4	C1-C2	0.28
4	D1-D2	0.77
5	C1-C2	0.46
5	D1-D2	0.68

Splice resistances with the new system are <u>consistent</u> with earlier measurements. The new system allows for simultaneous measurements of many segments.

All splices < 1 n Ω

8

V-I measurements with MUX (TC3)



This and other tests showed that quenches happen due to gradual approach to critical surface.

Office of

3/1/2021

ENERGY Science

... and we see resistance in some segments starting to grow with current as low as 2 kA

A characteristic V-I curve is observed **in the two segments quenching most** (would result in a very bad n-value) with the limiting one showing faster growth.

Some other segments are
 showing similar signs but at much
 8 lower level. Most segments don't show this behavior but some we can't measure.

Segments in MUX measurements



Differential resistances (2 kA to 6.8 kA) seen, some "bad" measurements omitted:

	<mark>></mark> 3b2_	_b1	3a8_a9	3a3_a4	3a5_a6	3a7_a8	3a9_b8	2a5_a4	gai	rbage	— 2a2_a1	— 3a1_a	2 2a8_a7	2b5_b6	2b7_b8	2a9_a8	2a7_a6
R(Ohm)	4.68	344E-10	2.11756E-11	5.6548E-11	3.95752E-09	8.04315E-12	-7.411E-12	-1.10342E-11	1.4	3998E-07	5.3581E-10	3.5946E-1	0 4.7827E-12	L 4.6585E-11	-2.225E-12	1.2455E-11	-4.149E-11
err(Ohm)	6.00)78E-12	1.08428E-11	4.68E-10	7.08039E-09	6.45922E-12	7.8616E-12	1.46786E-10	2.2	9114E-09	2.1663E-11	6.5192E-12	2 3.4921E-12	L 5.4112E-11	8.3124E-12	1.0306E-11	2.9946E-11
	- 5	5d1 2b1	5d4 d	3	5d2 d1	🗢 2b1 b2	2 2b3 l	b4 4d6	d7	- 4d1 d2	4d3	d4 🔷	4d5 d6	• 4d7 c7	Red/brow	n – bad/n	ot reliable
R(Ohm)	6.	.24479E-1	1.5	079E-08	9.94219E-1	LO 1.264E-:	4.58333	3E-11 -4.16		8.0191E-1	10 3.338	1E-10 3.	62641E-10	5.6793E-10	Purple	e – inconsi	istent
err(Ohm)	9.	.17173E-1	6.17	'918E-09	1.02358E-1	1.1103E-1	10 5.8363	BE-11 5.055	593E-11	8.77E-1	12 7.2714	1E-10 8.	29624E-12	1.2022E-11	(only o	one)	
•	<mark>_5c6</mark>	_c7	5c3_c4	— 50	:5_c6	— 5c7_d7	— 5d6_d5	4 c1_5c1	— 4c6_0	c5 4	lc4_c3 🛛 🗢	4c2_c1	— 5c1_c2		Green	- splices	
R(Ohm)	2.	.82422E-0	-2.674	411E-11	5.74708E-09	3.431E-10	6.1604E-10	4.283E-10	3.1885E	-10 1.9	68E-10 2.2	414E-10	3.535E-10	Dhue		interne de	walaaad
err(Ohm)		2.4848E-1	.1 1.04	173E-09	2.96407E-11	1.2418E-11	9.7945E-12	2 5.1613E-12	2.9243E	-11 7.35	68E-10 6.1	179E-12	7.0493E-12	Blue	– clear res	Istance de	eveloped

U.S. DEPARTMENT OF

Voltage rise and behavior before quench (TC3)



Acoustics

- □ In TC1 we failed to extract good data from "new" style sensors
 - ✓ We can't read anything above large noise
- □ In TC2/TC3 we read two sensors on both ends (plates) with 0.5-1 MHz
 - ✓ we had back up ones too ultimately, three out of four worked all the time
- □ We find the old style more reliable
 - ✓ Screw instead of glue for surface attachment
 - ✓ Single polarity power supply
 - ✓ More sturdy (easier to handle)

"new style"

3/1/2021



Office of

Science

.S. DEPARTMENT OF

"old style"



Current is not to scale ± 8000 -MDPCT1, TC3, Ramp 1 (it ended with a trip, not a quench) 2000 3E+08 4E+08 5E+08 1E+08 2E+08 32 767 corresponds to 5 V This abnormal event indicates huge This level is too mechanical disruption high to explain with 10000 regular behavior LE sensor -10000 **RE** sensor -20000

3E+08

4E+08

1E+08

2E+0

Acoustics was used to identify abnormal "events"

5E+08

6E+08 Index

Acoustics – MDPCT1, TC3



Machine learning with acoustics



U.S. DEPARTMENT OF

ENERGY

Office of

Science

3/1/2021

primarily Duc Hoang (2020 summer student)

14

Anomalous events visualization



U.S. DEPARTMENT OF

ERGY

Office of

Science

3/1/2021

primarily Duc Hoang (2020 summer student)

MDPCT1

Anomalies time distribution in MDPCT1b (2 sensors)

• Nearly all the detected events fall within 15 seconds.



3/1/2021

S. DEPARTMENT OF

Office of

Science



Median is around 2.5 seconds before quench

More in (https://ieeexplore.ieee.org/document/9354037) :

Intelliquench: an adaptive machine learning system for detection of superconducting magnet quenches

primarily Duc Hoang (2020 summer student)

Anomaly events in MDPCT1b quenches (log_{10} threshold $3.0 \rightarrow 1.6$)

Quench antenna



warm

LBNL: seven axially placed elements

cold

FNAL: two sets of six axially placed elements (each set faces a coil)



For the two quenches in layer 1 (MDPCT1) the QA and VT based locations are consistent within few cm. We also know the quench propagation velocity (~ 2 cm/ms) although, interestingly, there is some inconsistency between VT and QA data.





Temperature sensors in the bore

- In addition to sensors on the shell (top/bottom) two temperature sensors
 were installed in the bore (LE endshoe)
 ✓ Opposite site in azimuthal direction
- They showed bore temperature is sensitive to ramp rate

- After the temperature rises it recovers very slowly in practice it doesn't recover.
- Temperature rise rate is clearly dependent on current ramp rate. Typical current ramp rates keep us below 2 K in the bore before quench.

3/1/2021

Office of

Science



High ramp rates at TC2

Slow Scan Data vs. date

mdpct1b.FvtMonScribe.200701000000.000

200 A/s

V1_CuHolPentBuNegM_1,



3/1/2021

Science

Summary

- □ Voltage tap data in TC2/TC3 are very good
- □ VTs and QA in TC1 provide rich information about the two quenches in layer 1
- □ Very useful information from "MUX" (multi-channel nano-voltmeter) in TC3
- Important hints from acoustics obtained in TC2 and TC3
- Potential for "anomalous events" hunting with acoustics and machine learning (more hints/evidence)
- Bore temperature sensors of potential future use, good data for studies of inner layer events
 ✓ Could extend to in-magnet-body measurements?





MDPCT1 Training



- (-

Temperature and ramp rate quench current dependence



MDPCT1b

We saw a significant degradation after TC1 in TC2 and then more in TC3. The quench levels at the two temperatures at TC3 (1.9 K and 4.5 K) were reproducible within 10 A each.

Acoustics data analysis suggests it is plausible that this large degradation was caused by a loud mechanical event (longitudinally consistent will all relevant quenches) observed in the first ramp of TC3.



The quench current dropped more than 20% between TC2 and TC3 suggesting significant conductor degradation (same SSL vs temperature within one percentage point). Also, from TC1 to TC2 the current at 4.5 K dropped by ~9% (though the magnet was not fully trained in TC1).

S. DEPARTMENT OF

Office of

3/1/2021

Science

Acoustics – MDPCT1, TC3



This huge acoustic event is seen at this magnitude at the return end only



Quenches in MDPCT1, TC1



d3 (coil 5) – from coil fabrication

Note that there is only one quench in coil 5C (layer 3).

locations are not well known

U.S. DEPARTMENT OF

Quench locations in MDPCT1, TC2





- Those colors indicate quenches in different non-adjacent segments (often in different layers/coils)
- This color indicates fairly well known location

 This color indicates not so well known location
 Both colors (and only them) can
 have associated numbers which are
 the numbers of similar quenches

26

MDPCT1 RRR



MDPCT1b cold resistance ratio



No abnormal behavior in TC3 except 10% higher resistance in inner coils (which don't quench)

 $(\bigcirc$

TC3 quench pattern



D7 D1 D2 D4 D3 Lower layer 4 D6 C3 C4 Lower layer 3 C6 C1 C2

In TC3 all 1.9 K quenches were at ~7.82 kA and 4.5 K quenches at 7.03 kA (20 A/s). All quenches started in 5c6_c7 with a familiar

pattern to some TC2 quenches.

In TC2 this pattern was seen in the very beginning of training at 1.9 K as well as in all > 2.2 K quenches and high ramp rate quenches.

So the quenching segment (and pattern) changed from 5c5_c6 in the end of training at 1.9 K to 5c6_c7 in TC3 but remain the same at 4.5 K.

Quench profiles in TC2



U.S. DEPARTMENT OF

ENERGY Science

Office of

3/1/2021

Acoustics – MDPCT1, TC3



ENERGY Office of Science

Ø

Office of

3/1/2021

Ramp 1

The magnet (shell) rings at ~2.5 kHz for about 100 ms

Acoustics – MDPCT1, TC3



Ø