



U.S. MAGNET
DEVELOPMENT
PROGRAM

MDPCT1b Magnet Disassembly

Igor Novitski

US Magnet Development Program
Fermi National Accelerator Laboratory



U.S. DEPARTMENT OF
ENERGY

Office of
Science

MDP general meeting

March 31, 2021



MDPCT1b results from the cold test:


- training quench locations
- big acoustic signal and magnet degradation
- TF difference for two last cold measurements, test 1 and test 2

Focus on:

- structural integrity
- coil's condition



TF Difference for Two Last Cold Measurements, test 1 and test 2



Magnet lifting and rotation after disconnection from the top plate




Magnet lifting from the VMTF pit



Magnet rotation procedure




Magnet electrical check, leads and VTs disconnection, “pizza box” removal



Magnet leads disconnection



Lead's plate removal



Braking wire bundles

Bullets and bolts unloading




Bullets unloading at RE




End plate nuts unloading at RE

End Plates removal at LE



End plate nuts unloading at LE



L1/L2 end plate at LE

Magnet preparation and transportation to VMS



Magnet at IB3 ready for transportation




Magnet unloading at VMS

Milling work




Magnet set up for the end ring cutting



Milling of the weld-prep

Magnet at IB3 assembly table



Magnet on the assembly table at IB3



Lifting of the top shell




Removal of the yoke fillers

Clamped Iron Yoke



Transporting the iron yoke assembly from the shell to the clamping tooling

Magnet in Press and Clamps Removing



Strain gauges reading



Clamp extraction

Clamps Removing



Magnet iron w/o clamps under press load



Removed clamps on the table

Clamp Inspection with Dye Penetrant



Visual inspection of the clamp



“Painted” clamps on the table



Iron Yoke



Iron yoke w/o clamps in clamping tooling



Lifting of the top iron yoke




Top iron yoke

Coil Block Lifting




Lifting of the coil block




Bottom iron yoke

Coil Block on Rotation Table



Coil block on the rotation table is ready for the wiring work

Coil Block Disassembly



RE view of the coil block GI

Coil Block Disassembly




Lifting of the outer coil



Outer coil in the holding fixture


Outer Coil #5



Outer coil, inside view




Inter-layer insulation



Inside view after insulation removed

Outer Coils #4/5 – Inner Layer View, RE after Test 2


Coil 4



Pole turn
whitening


Quench locations
in many ramps

Coil 5




Outer Coil #4/5 – Inner Layer View, Pole Split after Test 2

Coil 4



Coil 5




Pole turn
whitening


delamination

Quench locations
in many ramps

Outer Coils #4/5 – Inner Layer View, LE after Test 2




Coil 4




Coil 5

Outer Coil #5 - Inner Layer View, LE


Before test



After test 1




After test 2






Outer Coil #5 – Inner Layer View, Pole Split


Before test



After test 1



After test 2



Outer Coil #5 - Inner Layer View, RE



Outer Coil, Inner Layer View, RE at Different Stages



After curing

After reaction

Before impregnation

After impregnation

After cold test

Outer Coil #5 – Outer Layer View after Test 2



Return End



Pole split



Lead End


Outer Coil #4 – Outer Layer View after Test 2



Return End




Pole split



Lead End

Inner Coil #2 - Inner Layer View after Test 2


LE



RE

Inner Coil #2 - Outer Layer View after Test 2


LE



RE

Inner Coil #3 - Inner Layer View after Test 2



LE



RE

Inner Coil #3 - Outer Layer View after Test 2

LE



RE



Summary and Next Step

- MDPCT1b disassembly completed as planned
new magnet structure worked as expected
- All structural parts (skin, iron laminations, AL clamps, end plates, rods) inspected,
no visual damage observed
- Coil block shimming corresponds to the assembly plan
TF shift needs further investigation
- A visual inspection of the outer coils (4 and 5) and inner coils (2 and 3) completed
all surface cracks relate to a relative motion of the coil parts

Next steps

- Coil SG's reading
- Coil size measurements
- Data analysis