


Updates



- **Lab added 100 daily entries last week (1550 Total / NSD 60)**
- **<http://transition.lbl.gov/>**
- **Office of Enforcement Visit - (May 24-28)**
 - **Looking at LBL0014 Training**
 - **6 NSD employees show deficient on NS-0119 / NS-0121**
 - **“Not Authorized to Work”**
- **Director’s Review – June 2-4**

Recent Incidents




B070A Water Leak

- Started in B070A-3347A (Clean Room)
- Water damage on second and first floors
- Caused by clogged drain in Fume Hood
 - Beaker fell and blocked a drain

Key Takeaways

- Chemicals and electrical equipment should be elevated off floor
- EH&S may have a slow response
- Don't assume facilities personnel know how to protect your equipment
- A lot of people involved: Bldg Manager, FAM, EH&S (Chem, Elec & Rad), PIs



Recent Incidents



B070 Liquid Argon Cylinder

- Cylinder delivered Friday for B070-141
- On Monday, cylinder vented so loud that researcher evacuated room
 - Researchers from lab next door also evacuated because of sound
- May have been faulty over-pressure valve and pressure building circuit
- Had similar event a few months earlier




Group has now implemented a cylinder checklist

Recent Incidents



B088 Ventilation

- Two weeks ago noticed a guage reading zero
- EH&S verified low air flow on glove box pass-out port
 - Assumed to be a clogged in-line filter
- This week found the same system with NO air flow
- HEPA Blower had tripped off
- Never notified by facilities



Remember to always check ventilation before you start to work



QUESTIONS?